

Multi-Meter LCD Display

This handy Multi-Meter can be used for the measurement of DC / AC voltage, DC current, Resistance, Diode and Transistor Test, and Audible Continuity Test. This meter is ideal for performing many checks used in radio and electronic testing, car electrics, household appliances, portable tools and similar equipment.

All test functions are easily accessible by rotating the 20 position range selector switch to the required function. The multi-meter has many features to facilitate safe use including overload protection, recessed input terminals, automatic negative polarity and over-range indication. Additional features include a rubber protective housing with integral stand for easy visibility, a large 3 1/2 digit LCD backlit display with auto power off and low battery indication.

Specifications:

Display: 3 1/2 digit LCD, Max reading 1999.

Measuring method: Dual-slope integration A/D converter.

Operating temperature: 0°C to 40°C (32°F to 104°F).

Dimensions: 138 x 69 x 31 mm.

Weight: approx. 170g (including battery).

CAT2 200/600V



FAIDETMULTI
£21.45 Ex VAT
£25.74 Inc VAT

Damp and Moisture Meter

A small, pocket sized damp and moisture meter that can be used to measure the moisture content in timber, paper, cardboard and hard materials such as mortar, concrete and plaster. The moisture content is displayed as a percentage reading on the LCD digital display that is equipped with a backlight function for use in dark environments. The meter can also be used to measure the ambient temperature and is compact, portable and easy to use. The meter is supplied with a probe cover for safe storage when not in use. 4x LR44 batteries included.

Specifications:

Measurement Range:

Wood: 6-42%,

Material: 0.2-2.0%,

Temperature: 0-40°C

Resolution:

Wood: 1%,

Hard Materials: 0.1%,

Temperature: 1°C/2°F



FAIDETDAMP
£25.90 Ex VAT
£31.08 Inc VAT

Portable Electronic Scale

Portable electronic scales are ideal for holiday luggage, fishing and many other applications where an accurate weight reading is required. The scale can measure weight in kilograms, pounds, and ounces. It has tare, zero, and overload functions. A LCD display with backlight allows easy reading and the scale is supplied complete with both a steel hook and nylon strap. Requires 2x AAA batteries. (NOT included).



Maximum capacity: 50kg



Tare Function
 This button resets the scale display back to zero when an empty container is placed on the scales, in order to subsequently display only the weight of the contents of the container.

FAISCALE50KG
£17.64 Ex VAT
£21.17 Inc VAT