

Digital Max-Min Thermometer

This thermometer records the highest and lowest temperatures reached throughout the day and night and displays them on a digital display until re-set.

Measures temperature in both Centigrade and Fahrenheit. Suitable for indoor and outdoor use and mercury free.


Specifications

Range: -40°C to +50°C

-40°F to +120°F

(Accurate to ±1 degrees) Length: 244mm (9.5in)

Instructions



Columns show the current temperature in both Celsius and Fahrenheit. The current temperature and the minimum, maximum recorded temperatures may be viewed in either Celsius or Fahrenheit. Minimum and Maximum temperatures are clearly shown in the digital display.

Resetting the digital display

Depress the reset button to return both readings on the digital display to the current ambient temperature. From this point the thermometer will begin making a fresh recording of the minimum and maximum temperatures.

To replace the battery (1 x AAA)

- 1. Remove the back cover by unscrewing the screw
- 2. Remove the battery from the product
- 3. Insert the battery ensuring that the positive and negative terminals are correctly aligned
- 4. Replace the cover
- 5. Press the reset button to record temperature

